



# TOREO-P650

---

## SW Release Notes

Version 0.9.4

**Table of Contents**

1 Introduction.....3

1.1 Purpose of the document.....3

2 Release information.....3

2.1 Release History.....3

2.2 Hardware Support.....3

2.2.1 TOREO-P650.....3

2.3 Changes.....4

2.4 Known issues.....4

3 Document Revision History.....5

A List of Figures and Tables .....6

## 1 Introduction

### 1.1 Purpose of the document

The purpose of this document is to give the necessary information about a new software release, regarding information how to build the software and changes to previous versions

## 2 Release information

This chapter contains the Release Notes for Revision **0.9.4** of the **TOREO-P650** firmware. It describes the supported hardware and software modules for this release as well as important notes and information about this product.

Product Name	TOREO-P650
Type of Release	Release
Delivery	Binary
Version	V0.9.0
Build Date	20.4.2023
File name	blttofapp_v0.9.4

### 2.1 Release History

Revision	Date	Type
Initial Release (V0.3.0)	21.12.2021	Initial
V0.4.0	16.03.2022	
V0.5.0	10.06.2022	
V0.7.0	29.07.2022	
V0.8.0	05.09.2022	
V0.9.4	20.04.2023	

Table 1 Release History

### 2.2 Hardware Support

#### 2.2.1 TOREO-P650

- V1.3.0
- V1.4.0

## 2.3 Changes

Changes applied to previous versions

Type	Description
bugfix	Fixed: ColorStreamParams and ColorStream2Params must have the exact same value (not only the resolution) to enable ROI.
Feature	Add JPEG compression for RGB images.
Feature	Add grey scale mode for RGB sensors.
Mod	Color Sensor ROI speed optimization.
Mod	Application log files gets rotated after each restart. Last five logfiles get kept.
bugfix	Improved stability

## 2.4 Known issues

### 3 Document Revision History

Version	Date	Author	Description
V0.9.0	26.04.2023	BRA	

Table 3.1: Revision history

# A    List of Figures and Tables

## Figures

No table of figures entries found.

## Tables

Table 1 Release History .....	3
Table 3.1: Revision history.....	5